


Client	Royal Mail Group Ltd 100 Victoria Embankment London EC4Y 0HQ	KEY:	P = Presumed Sample AWS = As With Sample	Beyond Remit of Survey Inaccessible Areas Asbestos Present Inspection Reference Location
Site Address	Cardiff West LAN/PAR, 635-637 Cowbridge Rd, Cardiff CF5 1AX BE 381.1			
Survey Reference	47572-185561-001			
Date of Survey/Inspection	25/05/18			
Surveyors	N Farzaneh			
PAGE 1 OF 1				
Not to Scale				

Ground Floor



Key

Drawing Information

Project ID	623261
Survey Location	Cardiff West DO
Plan Location	Ground Floor
Survey Date	10/05/2024
Surveyors	B. Phillips

Key

ACM	No Access Area
Scope of Survey	S Sample
Cross Reference	XR Positive Item
Presume	P Negative Item
Strongly Presume	SP Removed Item
Cable Route	

Client Information


Client	Royal Mail
Address	Royal Mail plc 100 Victoria Embankment London EC4Y 0HQ
Tel	04138203

Company Information

Company	Lucion Services
Address	Unit 7 Halifax Court Dunston Tyne & Wear NE11 9JT
Tel	0191 461 8999



Please note: Asbestos containing material locations are only INDICATIVE of the area of location; not the exact position of the material; refer report register for details. Marked asbestos material encountered at the time of survey is for indicative purposes only and is not exhaustive; the reader should read the report in full. Drawing NOT to scale.



Key

Drawing Information

Project ID	623261
Survey Location	Cardiff West DO
Plan Location	First Floor
Survey Date	10/05/2024
Surveyors Name	B. Phillips

Key

ACM	No Access Area
Scope of Survey	S Sample
Cross Reference	XR Cross Reference
Positive Item	P Positive Item
Negative Item	N Negative Item
Removed Item	SP Strongly Presume
Cable Route	

Client Information


Client	Royal Mail
Address	Royal Mail plc 100 Victoria Embankment London EC4Y 0HQ
Tel	04138203

Company Information

Company	Lucion Services
Address	Unit 7 Halifax Court Dunston Tyne & Wear NE11 9JT
Tel	0191 461 8999



Please note: Asbestos containing material locations are only INDICATIVE of the area of location; not the exact position of the material; refer report register for details. Marked asbestos material encountered at the time of survey is for indicative purposes only and is not exhaustive; the reader should read the report in full. Drawing NOT to scale.



Key

Drawing Information

Project ID	623261
Survey Location	Cardiff West DO
Plan Location	Externals
Survey Date	10/05/2024
Surveyors Name	B. Phillips

Key

ACM	No Access Area
Scope of Survey	S Sample
Positive Item	XR Cross Reference
Negative Item	P Presume
Removed Item	SP Strongly Presume
Cable Route	

Client Information

Client	Royal Mail
Address	Royal Mail plc 100 Victoria Embankment London EC4Y 0HQ
Tel	04138203

Company Information

Company	Lucion Services
Address	Unit 7 Halifax Court Dunston Tyne & Wear NE11 9JT
Tel	0191 461 8999



Please note: Asbestos containing material locations are only INDICATIVE of the area of location; not the exact position of the material; refer report register for details. Marked asbestos material encountered at the time of survey is for indicative purposes only and is not exhaustive; the reader should read the report in full. Drawing NOT to scale.

