

Room 101 – 4500 x 3060 - Bathroom 1700-1700

Room 102 – 4560 x 3155 - Bathroom 2200-2200

Room 103 – 4500 x 3678 - Bathroom 2180 x 2070


Room 104 – 4500 x 3260 - Bathroom 2310 x 2210

Room 105 – 4550 x 3260 – Bathroom 2110 x 2002

Room 106 – 4500 x 3335 – Bathroom/Kitchen 2660 x 2100


Room 107 -4500 x 3335 - Bathroom/Kitchen 2660 x 2100

1st Floor Plans




F55	ACCOMODATION CORRIDOR
F56	OFFICE No 110
F57	OFFICE No 109
F58 & F58A	BEDROOM No 107
F59 & 59A	BEDROOM 106
F60	CORRIDOR
F61	NOT USED
F62	BEDROOM(No 105)
F63	BED STORE OPPOSITE ROOM 110
F64	BEDROOM(No 104)
F65	BEDROOM(No 103)
F66	BEDROOM(No 102)
F67	BEDROOM(No 101)
F68	DOJO CORRIDOR
F69	DOJO OFFICE
F70	CR 11 FEMALE CHANGING
F71	TAFF 2 CORRIDOR
F71A	CUPBOARD IN TAFF 2 CORRIDOR
F72	CATERING CHANGING ROOM
F72A	SERVICE RISER
F73	TAFF 1
F74	TAFF 2
F75	CR 10 MALE CHANGING
F76	ICE BATH ROOM
F77	MULTI CHANGE
F78	CR11 FEMALE WC/SHOWER
F79	CR 10 MALE WC/SHOWER
F80	DOJO FOUNTAIN ROOM
F80A	DOJO DRYING ROOM
F81	DOJO CORRIDOR
F82	DOJO MAT AREA
F83	DOJO CORRIDOR TO DRYING ROOM


Accommodation room 101 Upgrade





An asbestos demolition survey will be carried out on Monday 25th March with results on Tuesday 1st April.

Removal of fixtures unaffected by survey to commence Wednesday 1st April.










Accommodation
Room 105



Room 106 & 107

