



Notes

1. Drawing not to scale.

Schedule of repairs

1. Diagonal crack - REM 1
2. Vertical crack - REM 2
3. Vertical crack - REM 2
4. Diagonal crack - REM 1
5. Vertical crack - REM 2
6. Diag/Vert crack - REM 2
7. Vertical crack - REM 2
8. Horizontal crack - REM 2
9. Vertical crack - REM 2
10. Horizontal gap/crack - REM 2
11. Horizontal gap - REM 2
12. Vertical crack - REM 2
13. Vertical crack - REM 2
14. Vertical crack - REM 2
15. Vertical crack - REM 2
16. Vertical crack - REM 2
17. Vertical crack - REM 2
18. Vertical crack - REM 2
19. Vertical crack - REM 2
20. Vertical crack - REM 2
21. Diagonal crack - REM 1
22. Vertical crack - REM 2
23. Vertical crack - REM 2
24. Horizontal gap - REM 2

Rev.	Date.	Details.	By.	Chk.	
Amendments					



Bear Structures
Rugged by design

35 Stow Park Circle Newport NP20 4HF
United Kingdom info@bearstructures.com

Project:
37 THE WALK, NEW INN, PONTYPOOL

Title:
SURVEY PHOTO ID

Drawn: AB Checked: AB Scale(s) at A1: NTS

Date: 25.07.25 Job No. P0560 Drawing No. SK06s Revision: - Suitability: -

Drawing Status: FOR INFORMATION