

Photo Log



Front of shops and car parking area



Double and single chimney stacks to front of block



Cracking to external envelope



Electrical supply cables to rear elevation



Extraction unit from Chinese takeaway



Downpipes built into external walls to front



Downpipes exiting building fabric to rainwater gulley





Stepped cracking to brickwork at side of outbuilding



Cracking to brickwork to front of outbuildings



Cracking to brickwork on outbuildings



Damaged asbestos roof sheets to front elevation of outbuildings



Stepped cracking to outbuildings



Soil vent pipes extending through soffit and roof at eaves level